


CHARACTERIZATION AND REPAIR OF INTERNAL EROSION IN SANDSTONE FOUNDATION

By J-J FRY & G. JORGE

INTERNAL EROSION IN DAM FOUNDATION

From the 2 hereunder failure paths of internal erosion:

1. 213 piping through the embankment
2. 44 piping through the foundation or of the embankment into the foundation



Internal erosion through foundation is less easy to characterize than through embankment

LESSONS LEARN FROM DAM ACCIDENTS

- BOUZEY (1895)
- TIGRA (1917)
- GLENO (1923)
- FLAGSTAFF (1963)
- FONTENELLE (1965)
- SISGA (1979)
- ITIYURO (1981)



Weathered Sandstone Foundations are most susceptible to internal erosion

CHARACTERIZATION TESTS FOR DAM FOUNDATION

Emphasis is put on two investigation tests to characterize the susceptibility of the sandstone foundation to be eroded

1. The drilling recording
2. The Water tests


1- Drilling Recording

« DUR » = Hardness


$$\text{Hardness} = P \cdot C / V$$

- P : vertical pressure
- C : torque
- V : tool rate

Hardness of the rock is characterized by
Drill machine : F320
with tricone VH1



Water Critical Pressure




2 – Water Lugeon tests

2 new parameters:


Critical pressure P_c
 limit of linearity
 between pressure
 and discharge rate
Opening ratio K_f/K_o

■ K_o : initial permeability


■ K_f : final permeability




a1-Ecoulement laminaire en milieu homogène




a4-Ecoulement turbulent en milieu homogène




a2-Ecoulement laminaire, colmatage à haute pression



a5-Ecoulement turbulent, colmatage progressif




a3-Ecoulement laminaire, débouillage à haute pression



a6-Ecoulement turbulent, débouillage progressif


Lessons from ITIYURO dam incident



Internal erosion in Sandstone Dam Foundations


R263 31/08/12

Lessons from ITIYURO dam



Leakages caused internal erosion in the sandstone foundation ($>1000\text{m}^3$) Sinkholes occurred in the rockfill crest and upstream face

Application to ITIYURO dam




weak sandstones which suffered internal erosion have very low hardness values :

$$\text{DUR} < 20.$$


Investigations of ITIYURO dam

- weak sandstones areas suffering internal erosion have :
- low critical pressure $P_c < 0,4 \text{ MPa}$
- Lugeon Permeability $K > 15 \text{ Lugeon}$


Initial permeability



Correlation between P_c and Cohesion




Correlation between P_c and porosity



Experience from other dam incidents

BORDE SECO suffered internal erosion
Diaphragm wall was required



Internal erosion in Sandstone Dam Foundations
R263 31/08/12

Criteria from dam incidents

Parameters	Unity	ITIYURO		BORDE SECO		LAS CUEVA		LA HONDA	
Statistics		min	Max	min	Max	min	Max	min	Max
P_c	100 kPa	0	2	0,4	2	0	2	0	1
K_o	LU	35	50	16	57	75	135	15	36
$O_c = K_f/K_o$	-	3	8	3	6	2	4	2	4
Dur	-	0	20	0	10	0	10	0	10

Observed limits between erodable and no-erodable rock

Final assessment of criteria of area susceptible to be eroded

PROPOSED CRITERIA

Critical Pressure : $P_c < 0,2 \text{ MPa}$

Hardness : $Dur < 10$

Opening Criterion : $O_c > 3$

Initial Permeability: $K_o > 15 \text{ UL}$

CONCLUSION : PROPOSED DESIGN CRITERIA

New parameters are proposed from drilling recording and water tests to characterize the resistance to internal erosion of sandstone foundations.

Depth of diaphragm wall : depth where the pore pressure under the full reservoir is lower than the critical pressure and the opening criterion is lower than 2 and $Dur > 20-30$.