



# Classification of the Eroded Cavings behind Concrete-faced Embankments by Ground-Penetrating Radar

Jian-Hong Wu

Dept. Civil Engineering,

National Cheng Kung University,  
Tainan, Taiwan



# Outline


---

- Introduction
- Investigated river dikes
- Research method
- Research results
- Conclusions

# Introduction



- Concentrating rainfalls in plum rain and typhoon seasons often cause floods in Taiwan.
- The flood along Tsengwen River in southern Taiwan caused by Typhoon Nari in September, 2010.
- The flooding area was about 1,293 ha, and the total loss was about 8 million USD.







# Introduction

---

- The mechanism of the erosion at the river embankments are:
  - (1) The river water scours out the earth fill at the bottom of dike and generates cavities behind the concrete plates.
  - (2) Rainwater infiltrates to the joints and cracks on concrete plates and erodes the earth fill behind.
- The river water scouring can be determined by the scouring effect at the toe of the river dike.
- Erosions caused by the rainfall infiltration is difficult to be detected visually because the concrete plate is thick and rigid.
- In the early stages of erosions, insignificant signs of damage can be observed on the concrete plates.

\*Non-destructive testing method? GPR?


# Investigated river dikes



- Shan-shang embankment was built between 1998 and 2011.
- This section is close to the river trench (about 40-70 m) and often scoured out by the stream.
- The land side slope has 1 step concrete-faced, and the river side slope has 2 steps .




# Research method



- A 400MHz antenna is used in this study.
- The wave velocity of the concrete and soils is assumed to be 0.1 m/ns.
- The maximum two-way travel time is set 50 ns in this study with the maximum signal penetration depth is 2.5m.


# Research results




(a)



(b)



(c)



GPR detection at another dike



# Research results

No. of concrete plate		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
Survey line	1-1	1	2	2	2	2	1	1	1	1	1	1	1	1	1	1	1	1	1	2	2	1	2
	1-2	3	3	2	1	1	2	3	3	2	2	1	1	1	2	2	1	1	1	1	1	2	2
	2-1	2	3	3	3	4	4	2	1	1	1	2	1	2	2	1	1	1	1	1	1	1	1
	2-2	3	3	3	3	3	3	3	1	2	1	1	1	1	2	1	1	3	3	3	3	1	2
	3-1	1	3	3	3	3	3	3	2	1	2	2	3	1	2	1	1	1	1	1	1	4	3
	4-1	3	3	3	3	4	3	3	3	3	3	3	3	3	3	3	4	4	3	4	3	5	2

No. of concrete plate		23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43
Survey line	1-1	2	2	2	1	2	2	3	3	3	3	3	3	3	3	3	2	2	2	2	2	2
	1-2	2	1	3	2	3	1	2	2	2	2	1	3	3	3	3	3	3	3	1	1	1
	2-1	1	2	3	3	3	3	2	2	2	1	3	3	4	3	3	3	2	2	2	1	2
	2-2	1	1	3	3	3	3	3	3	3	3	1	1	1	1	3	3	1	2	3	3	3
	3-1	3	4	1	2	2	1	1	2	1	1	1	2	4	1	3	1	2	1	1	1	1
	4-1	3	4	2	2	3	3	2	2	2	2	2	3	2	4	3	4	2	2	3	2	3





# Research results

---

- The erosion degree of each span can be assembled after classifying the erosion degree obtained from the survey lines at the crown, upper slope, mid platform, and lower slope.
- High erosion degree occurs at Spans 2 to 7 and Span 34 to 37.
- High erosion degree can be found at Line 4-1, showing that the toe of the embankments were eroded severely by the river.
- The engineers can identify the locations of high erosion degree from the figure and analyze the mechanism of embankment erosions.



# Conclusions

---

- In this study, the erosion degree of concrete-faced dikes was investigated by the length and depth of the eroded cavities using GPR.
- The erosion degree of each span of the dikes was classified.
- Since the severely eroded areas can be discovered, we can decide the priority of maintenance to the river dikes after putting the erosion degree of each span together.
- The GPR images provide detail information for further study on the possible causes of dike erosion.



---

Thank you for your patient