



PIANC

The World Association for Waterborne
Transport Infrastructure

COATING BASED CORROSION MITIGATION FOR HYDRAULIC STEEL GATES



InCom Working Group N° 190 – April 2024

PIANC REPORT N° 190

INLAND WATERWAYS AND PORTS COMMISSION

COATING BASED CORROSION MITIGATION FOR HYDRAULIC STEEL GATES

April 2024

PIANC has Technical Commissions concerned with inland waterways and ports (InCom), coastal and ocean waterways (including ports and harbours) (MarCom), environmental aspects (EnviCom) and sport and pleasure navigation (RecCom).

This report has been produced by an international Working Group convened by the Inland waterways Commission (InCom). Members of the Working Group represent several countries and are acknowledged experts in their profession.

The objective of this report is to provide information and recommendations on good practice. Conformity is not obligatory and engineering judgement should be used in its application, especially in special circumstances. This report should be seen as an expert guidance and state-of-the-art on this particular subject. PIANC disclaims all responsibility in the event that this report should be presented as an official standard.

PIANC HQ
Boulevard du Roi Albert II 20 B. 3
1000 Brussels | Belgium

<http://www.pianc.org>

VAT BE 408-287-945

ISBN 978-2-87223-040-2

© All rights reserved

TABLE OF CONTENTS

LIST OF FIGURES	6
LIST OF TABLES	7
EXECUTIVE SUMMARY	8
1 General Aspects	9
1.1 Scope	9
1.2 Introduction.....	9
1.2.1 Terms of Reference	9
1.2.2 Structure of the Report.....	10
1.2.3 Members of the Working Group	10
1.2.4 Meetings.....	11
1.2.5 Acknowledgements.....	11
2 Corrosion & Hydraulic Gates	12
2.1 Corrosion Overview.....	12
2.2 Forms of Corrosion	13
2.3 Rate of Corrosion.....	14
2.4 Accelerated Low Water Corrosion	14
3 Corrosion Mitigation Coating Systems	15
3.1 Selection of the Correct Corrosion Protection System	16
3.2 Types of Paint.....	16
3.2.1 Epoxy	17
3.2.2 Vinyl.....	18
3.2.3 Polyurethane and Polyurea.....	18
3.2.4 Hot Dip Galvanising.....	18
3.2.5 Spray Metalizing/Thermal Spraying	19
3.2.6 Cathodic Protection	20
4 Surface Preparation	22
4.1 Surface Preparation Overview.....	22
4.2 Details of Surface Preparation Methods	23
4.2.1 Solvent Cleaning	23
4.2.2 Abrasive Blasting.....	23
4.2.3 Water Jetting	24
4.2.4 Hand Tool and Power Tool Cleaning.....	25
4.3 Rust Grades.....	25
4.4 Hazardous Material	25
5 Coating Applications	27
5.1 Coating Application Overview.....	27
5.2 Brush and Roller	27
5.3 Spray	28
5.3.1 Conventional Spray	28
5.3.2 Airless Spray.....	28
5.3.3 Plural Component	28
5.4 Coating Applicator and Inspector Certifications	28
5.4.1 Flemish Government, Belgium	29
5.4.2 Dutch Government, the Netherlands	29
5.4.3 American Government, United States of America.....	29
5.4.4 German Government, Germany.....	29

5.5	Specifications.....	30
5.5.1	Flemish Government, Belgium	30
5.5.2	Dutch Government, the Netherlands	30
5.5.3	American Government, United States of America.....	31
5.5.4	German Government, Germany.....	32
6	Case Studies	33
6.1	Belgium.....	33
6.1.1	Lock Structure	33
6.1.2	Location Characterization	33
6.1.3	Lock Renovation.....	34
6.1.4	Coating System	37
6.2	The Netherlands.....	38
6.2.1	Dam Structure.....	38
6.2.2	Location Characterization	40
6.2.3	Current Coating System after Total Refurbishment (Blast Cleaning)	40
6.2.4	Project Cost.....	42
6.2.5	Lifetime Expectancy	42
6.2.6	Lifecycle Cost	42
6.3	United States	43
6.3.1	Introduction.....	43
6.3.2	Coating System Overview	43
6.3.3	Project Cost.....	45
6.4	Germany	46
6.4.1	Introduction to the Main Danube Canal	46
6.4.2	Location Characterisation.....	46
6.4.3	Previous Coatings	46
6.4.4	New Corrosion Protection System.....	47
6.4.5	Experiences with the Corrosion Protection Coating	49
6.4.6	Project Duration and Costs	49
7	Recommendations & Conclusions	51
7.1	Recommendations.....	51
7.2	Conclusions.....	53
8	REFERENCES.....	54
	APPENDIX A: TERMS OF REFERENCE.....	58
	APPENDIX B: GLOSSARY, ABBREVIATIONS AND SYMBOLS.....	59
	B.1 Glossary	59
	B.2 Abbreviations.....	60
	B.3 Units.....	61
	APPENDIX C: Types of Gates	63
	C.1 Miter Gates.....	63
	C.2 Tainter Gates.....	64
	C.3 Single Pivot Gates.....	64
	C.4 Sector Gates	64
	C.5 Rotating Gates (Flap Gates)	65
	C.6 Wicket Gates	67
	C.7 Rolling Gates.....	67
	C.8 Vertical Lift Gates	69
	APPENDIX D: Gate Equipment.....	71
	APPENDIX E: Calculation for the Rate of Corrosion.....	72

LIST OF FIGURES

Figure 1: Corrosion cell at the surface of an iron object (Image generated by M Schmid, BAW (2023) ..	12
Figure 2: Typical corrosion rate profiles along water front steel structures. (Image generated by R. Wilson, USACE (2024))	14
Figure 3: A well applied stripe coat [De Baere, 2017]	27
Figure 4: (a) Location of the Pierre Vandamme Lock in the Port of Zeebrugge; (b) Plan view of the lock complex [Hillewaere, Blontrock & Missinne, 2020]	33
Figure 5: (a) Cross section of the lower lock head; (b) Side view of one of the rolling lock gates [Hillewaere, Blontrock & Missinne, 2020]	34
Figure 6: (a) Lifting operation of lock gate, March 2018; (b) Lock gate n°4 at the working location [Hillewaere, Blontrock & Missinne, 2020]	35
Figure 7: (a) Bulkhead caisson to put the gate recesses in dry conditions; (b) Configuration with bulkhead and habitat caisson to put both the gate recess as well as the rails of the LRW in dry conditions [Hillewaere, Blontrock & Missinne, 2020]	36
Figure 8: The new rail system of lock gate n°4 (and n°1) [Hillewaere, Blontrock & Missinne, 2020]	37
Figure 9: The Haringvliet Dam (Photo taken by Carolien Nieuwland, RWS)	39
Figure 10: The Haringvliet Dam, from river (Source: Beeldbank, RWS)	39
Figure 11: The Haringvliet Dam (Source: Beeldbank, RWS)	39
Figure 12: Location of the Haringvliet Dam (Source: Google Maps)	40
Figure 14: Tainter gate – river side Epoxy system (Photo taken by Carolien Nieuwland, RWS)	41
Figure 13: Building of the lock, coal tar epoxy on steel (Source: Beeldbank, RWS)	41
Figure 15: USA Applicator Certification on ASTM D4228 Test Plate (Photo taken by Brooke A. Divan, USACE)	43
Figure 16: L&D 22 Tainter Gate (Photo taken by Brooke A. Divan, USACE)	45
Figure 17: The Lock Erlangen – lower gate (Photo provided by WSA Donau MDK)	46
Figure 18: The Lock Berching – upper gate (Photo provided by WSA Donau MDK)	47
Figure 19: Primer with imperfections (Photo provided by WSA Donau MDK)	47
Figure 20: Examples of field joints coated with primer (Photo provided by WSA Donau MDK)	48
Figure 21: Fasteners assembled 'wet in wet' (Photo provided by WSA Donau, MDK)	48
Figure 22: PIANC WG 190 Site Visit to Maeslantkering Storm Surge Barrier on the Nieuwe Waterway (Photo taken by Brooke A. Divan, USACE)	51
Figure 23: Mitre gates in the USACE Nashville District (Photo taken by Brooke A. Divan, USACE)	63
Figure 24: Tainter gate in Spandau (Havel) (Photo provided by Federal Waterways Engineering and Research Institute under CC-BY 4.0 license)	64
Figure 25: Seabrook Sector Gates in New Orleans District, USACE (Photo submitted by Carl Balint, MVN, USCAE)	65
Figure 26: Flap (tumble) gate, view from the upstream direction, old Wusterwitz lock, Elbe Havel Canal (Photo provided by Federal Waterways Engineering and Research Institute)	66
Figure 27: Flap (tumble gate), gate pit and inlet of the filling system on the upstream side, old Wusterwitz lock, Elbe Havel Canal. (Photo provided by Federal Waterways Engineering and Research Institute)	66
Figure 28: Full-scale Olmsted Wicket Gates on Ohio River, Louisville District, USACE (EM 1110-2-2703)	67
Figure 29: Gate with hydrostatic slide bearings, Krammersluizen (Photo taken by Carolien Nieuwland, RWS)	68
Figure 30: Sliding gate at Nieuwe Oranjesluis in Amsterdam during installation in 1994 (Beeldbank, RWS)	68
Figure 31: Zandvliet Lock, Belgium, Rolling gate in closed position (EM 1110-2-2610)	69

Figure 32: Rolling gate machinery, Van Cauwelaert Lock, Antwerp, Belgium (EM 1110-2-2610)..... 69

Figure 33: Lift gate at Prins Beatrix sluis in Nieuwegein (© Rijkswaterstaat | Eli Gehasse)..... 70

Figure 34: Vertical lift gate in New Orleans District, USACE (Photo taken by Brooke A. Divan, USACE)..... 70

LIST OF TABLES

Table 1: Typical corrosion rates in different water systems..... 15

Table 2: Comparison of Surface Preparation Standards..... 22

Table 3: Water jetting (SSPC-SP 12/NACE No. 5, 2002; ISO 8501-4, 2020) 24

Table 4: Estimated costs for total refurbishment of a Tainter Gate Haringvliet Dam..... 42

Table 5: Estimated costs for touch up of a Tainter Gate Haringvliet Dam 42

Table 6: System 5-E-Z Paint Schedule (UFGS 09 97 02, FEB 2020) 44

Table 7: System 3-A-Z Paint Schedule (UFGS 09 97 02, FEB 2020)..... 44

Table 8: System 6-A-Z Paint Schedule (UFGS 09 97 02, FEB 2020)..... 45

Table 9: Price estimation of the coating project..... 49