



PIANC

InCom WG Report n° 191 - 2020



COMPOSITES FOR HYDRAULIC STRUCTURES

The World Association for Waterborne Transport Infrastructure



PIANC
The World Association for
Waterborne Transport Infrastructure

PIANC REPORT N° 191
INLAND NAVIGATION COMMISSION

COMPOSITES FOR HYDRAULIC STRUCTURES

2020

PIANC has Technical Commissions concerned with inland waterways and ports (InCom), coastal and ocean waterways (including ports and harbours) (MarCom), environmental aspects (EnviCom) and sport and pleasure navigation (RecCom).

This report has been produced by an international Working Group convened by the Inland Navigation Commission (InCom). Members of the Working Group represent several countries and are acknowledged experts in their profession.

The objective of this report is to provide information and recommendations on good practice. Conformity is not obligatory and engineering judgement should be used in its application, especially in special circumstances. This report should be seen as an expert guidance and state-of-the-art on this particular subject. PIANC disclaims all responsibility in the event that this report should be presented as an official standard.

PIANC Secrétariat Général
Boulevard du Roi Albert II 20, B 3
B-1000 Bruxelles
Belgique

<http://www.pianc.org>

VAT BE 408-287-945

ISBN 978-2-87223-006-8

© All rights reserved

TABLE OF CONTENTS

1	General Aspects	5
1.1	Introduction	5
1.2	Objective	5
1.3	Structure of the Report	5
1.4	Related PIANC Reports	6
1.5	Members of the Working Group	6
1.6	WG 191 Meetings.....	8
1.7	Potential Impact of the Guidance	8
1.8	Terms of Reference.....	8
1.9	Acknowledgements	8
2	Introduction to Composites.....	9
2.1	Introduction	9
2.2	FRP Constituents	9
2.2.1	Fibres	9
2.2.2	Resins	9
2.2.3	Additives and Other Ingredients	10
2.3	Manufacturing of Composites.....	10
2.3.1	Pultrusion	10
2.3.2	Resin Transfer Molding	11
2.3.3	Vacuum-Assisted Resin Transfer Molding.....	12
2.3.4	Wet Lay-Up/Hand Lay-Up	12
2.3.5	Compression Molding.....	12
2.4	Composites Properties.....	13
2.5	Applications.....	13
3	Characteristics and Failure Modes of Composites	15
3.1	Characteristics of Composites.....	15
3.1.1	High Strength-and Stiffness-to-Weight Ratio	15
3.1.2	Durability	15
3.1.3	Long-Term Water Submersion Resistance.....	16
3.1.4	Chemical Resistance	16
3.1.5	Ultraviolet Resistance.....	17
3.1.6	Thermal degradation	17
3.1.7	Hydrothermal.....	17
3.1.8	Low Temperature and Freeze-Thaw (FT) Cycling.....	17
3.1.9	Fire Resistance (FR)	18
3.1.10	Fatigue Evaluation.....	18
3.2	Types of Failures.....	20
3.2.1	Failure of Polymer Composites.....	20
3.2.2	Failures from Process and Production Variabilities	21
3.2.3	Failures under Environmental Variations.....	22
3.3	Recycling and Green Composites	23
3.4	Concluding Remarks.....	23
4	Hydraulic Structural Applications: Case Studies	24
4.1	Mitre Blocks.....	24
4.2	Underwater Wrapping of Concrete Ports.....	25
4.3	Wicket Gates.....	26
4.4	Recess Panels	27
4.5	Rehab of Corroded Steel Piles.....	28
4.6	Lock Gates and Stop Logs	29
4.7	Structural Repair and Protection System	31
4.8	Composite Dolphin.....	32
4.9	Composite Lighthouse.....	33
4.10	SuperLoc Fibreglass Reinforced Polymer (FRP) Sheet Piling and Accessories	34
4.11	Composite Pilings Protect Platinum LEED Site from Flooding	34
4.12	Composite Pilings Alter Course of Erosion.....	35
4.13	Fibreglass Structures Stand the Test of Time Offshore.....	35
4.14	Fibreglass Structures Used to Reclaim Beaches	36

4.15	FRP Products Aid in the Rehabilitation of Endangered Species	36
4.16	Materials Guard a California Pier from Corrosion.....	37
4.17	FRP Arctic Towers Project	38
4.18	DURADEK in Olympic Pool Operation	38
4.19	Fibreglass Floating Docks Save High Maintenance Costs.....	39
4.20	Fibreglass Grating Stays Shipshape Longer	39
4.21	DURADEK Platforms and Catwalks Save LaGuardia Millions in Maintenance Costs	40
4.22	Fibreglass Fights Corrosion ‘Underwater’ and Above	41
4.23	Phenolic Grating- Lightweight Offshore Decking	41
4.24	Movable Pool dividers that are Long-Lasting	42
4.25	Strongwell’s Pultruded Grating for a Florida Marina	42
4.26	Round Safrail	43
4.27	SAFPLANK – The Ideal Material for a Pier Deck	44
4.28	STRONGDEK™ Ocean Front Fibreglass Decking Impervious to salt water Environment	44
4.29	Glass Fibre Reinforcement by ComBAR®	45
4.30	Panels, Pipes and Posts	46
4.31	Pont y Ddraig (Bridge of the Dragon) Foryd Harbour	46
4.32	Large-Scale Composite Bumper System for Bridge Pier Protection Against Ship Collision	47
4.33	Reinforced Plastic Inspection Walkway	47
4.34	Hoover Dam Penstock Tunnels.....	48
4.35	Drop Protection for Subsea Applications.....	49
4.36	Bellagio Hotel and Casino Fountains	49
4.37	Aids to Navigation (ATON) Structures	50
4.38	Subsea Cocoons.....	50
4.39	Concluding Remarks	51
5	Design METHODS FOR Composite Structures.....	52
5.1	Introduction	52
5.2	Overview of Development of American FRP Standards.....	52
5.3	Overview of Development of European FRP standards	53
5.4	Reduction Factors Used in Pre-Standard for Load and Resistance Factor Design (LRFD) of Pultruded Fibre Reinforced Polymer (FRP) Structures.....	53
5.5	Design of FRP Recess Panel.....	54
5.6	Design of FRP Wicket Gate	54
5.7	Design of FRP Blocks for Mitre Gates.....	57
5.8	Repair of Corroded Steel Piles with FRP	58
5.9	Design Steps of a FRP Composite Lifting Gate	60
5.9.1	Introduction.....	60
5.9.2	Design Requirements and Assumptions.....	61
5.9.3	Material Selection	61
5.9.4	Structural Concepts	61
5.9.5	Deflection Requirements	62
5.9.6	Cost Comparison.....	62
5.10	Concluding Remarks.....	62
6	Inspection and Maintenance.....	63
6.1	Infrared Camera and Heating System	63
6.2	Digital Tap Hammer	64
6.3	Fibre Optical.....	65
6.4	Sample Field Testing Results.....	65
6.5	Repair and Maintenance	66
6.6	Concluding Remarks.....	66
7	Cost Considerations.....	67
7.1	Need for Cost Analysis.....	67
7.2	Methods of Cost Analysis.....	67
7.2.1	Initial Costs.....	67
7.2.2	Life Cycle Costs.....	67
7.3	Case Study: Initial Future Cost for FRP Bridge Decks	69
7.4	Case Study: LCC Analysis on FRP Bridge Deck Applications	69
7.5	USACE Experiences	69
7.6	Europe Experience.....	71

7.7	Conclusions.....	71
8	SUMMARY	72
9	REFERENCES.....	73
	APPENDIX A: GLOSSARY OF TERMS	85
	APPENDIX B: OUTSTANDING TECH PAPER AT CAMX 2019.....	89

LIST OF FIGURES

Figure 1.1	Group photo of WG 191 members who attended the June 2017 meeting in the Netherlands. Left to right: Jonathan, Martijn, Jos, Wouter, Liesbeth, Hota and John.
Figure 2.1	Pultrusion of 4' Wide GFRP Composite Sandwich Panels with Integral Joint Edges
Figure 2.2	RTM process
Figure 2.3	Compression molding process
Figure 2.4	Thirty-five (35) tonnes CFRP of fuselage, wings, tail, gates and interior are used in each 787
Figure 2.5	Ocean Gate (Everett, WA, US) announced on 27 June 2019 the successful unmanned depth test of the manned submersible, Titan, to validate the hull to a depth of 4,000 m (13,123 ft)
Figure 2.6	Startlink House. Startlink is a pultruded glass reinforced composite component kit which can be rapidly assembled into a wide variety of low-rise building forms without metal fastenings
Figure 3.1	Cracking initiation and growth of a sandwich sample under 3 pt bending fatigue, leading to eventual failure at the corner (WVU-CFC)
Figure 3.2	Different shapes of composite structures
Figure 3.3	Honey-comb structure
Figure 3.4	Sandwich laminate failure modes (adapted from Det Norske Veritas Offshore Standard DNV-OS-C501, Composite components, 2003)
Figure 4.1	Mitre gate (left); Mitre block (right)
Figure 4.2	Single GFRP Block (4"x2.5", 55 % fibre volume) with Max. Failure Load >224 (kips)
Figure 4.3	View of Discharge Ports at Chickamauga Lock and Dam, TN
Figure 4.4	(a) Aqua Wrap; (b) Onboard Audio, Video, and Depth Monitoring; (c) Under Water
Figure 4.5	Deteriorated Wood Wicket Gate Pulled from Service
Figure 4.6	Composite Wicket Gate (Left) and Prototype Gate under Bending
Figure 4.7	Composite Wicket Gates in Service
Figure 4.8	(a) Steel Recess Panel; (b) FRP SuperDeck Component; (c) SuperDeck with Polyuria Coating; (d) Assembly with Steel Frame
Figure 4.9	East Lynn Bridge Rusted and Scoured at Mudline
Figure 4.10	Rehabilitation Steps of Steel Piles with FRP Composites
Figure 4.11	Werkendam FRP Lock Gates
Figure 4.12	Erica Ter Apel Lock Gates (Provinces Groningen & Drenthe, the Netherlands)
Figure 4.13a	World's Largest FRP Lock Gates in the Wilhelminakanaal Tilburg
Figure 4.13b	The FRP lock gates in the Wilhelminakanaal
Figure 4.13c	Flood protection FRP lifting gate at 'Afsluitdijk' fish passage
Figure 4.14	FX-70 Structural repair and protection system of Simpson strong-tie
Figure 4.15	Before (left) and after (right) foundations repairs of Chesapeake Bay Bridge
Figure 4.16	FRP Dolphin (Fuerteventura, Canary Islands, Spain, 2014)
Figure 4.17	FRP lighthouse in the north extension of Valencia Port (Valencia, Spain, 2015)
Figure 4.18	CMI'S UltraComposite™ UC 95 profile sheet piling for flood wall
Figure 4.19	Walls made of UltraComposite™ UC 30 sheets
Figure 4.20	All-fibreglass well bay deck for 18 wellheads on Shell's Southpass 62A production platform
Figure 4.21	The Martin Beach Builder™, a new triangular framing system anchored to a precast concrete base
Figure 4.22	FRP lifting and lowering platform made from Strongwell products to rehabilitate the manatees
Figure 4.23	The Avila Beach Pier in California reconstructed using Strongwell's pultruded fibreglass structural materials
Figure 4.24	FRP arctic towers for a Seal Observation Facilities Project on St. Paul Island, Alaska
Figure 4.25	The Olympic pool in Oklahoma City, Oklahoma
Figure 4.26	Fibreglass floating docks in Snohomish County, Washington State
Figure 4.27	Fibreglass grating manufactured by Strongwell used by Delta Marine, Seattle, WA.
Figure 4.28	DURADEK platforms and catwalks

- Figure 4.29 SAFRAIL™ fiberglass handrail systems used in the Mall of America's
- Figure 4.30 DURAGRID® phenolic grating used in Shell Mars tension leg platform in the Gulf of Mexico
- Figure 4.31 Movable swimming pool divider bulkheads, manufactured by Recreation Supply Company
- Figure 4.32 Strongwell's DURAGRID® T-1700 pultruded grating used on piers at Dinner Key Marina in Miami, Florida
- Figure 4.33 Strongwell's round SAFRAIL™ industrial handrail system in Fort Lauderdale, Florida
- Figure 4.34 Strongwell's SAFPLANK® fiberglass plank system for the pier's deck
- Figure 4.35 STRONGDEK™ installed at Perdido Beach Resort in Orange Beach, Alabama
- Figure 4.36 Glass Fibre Reinforcement by ComBAR (Fibreline Composite)
- Figure 4.37 FRP Handrail, Ladder, Platform and Walkway for Sea Waterfront Facilities
- Figure 4.38 Cycle/Footbridge across the River Clwyd at Rhyl Harbour, North Wales
- Figure 4.39 Applications of LCBS on bridge protection projects in China
- Figure 4.40 Blennerhassett Island Bridge
- Figure 4.41 PROForms structural fiberglass shapes
- Figure 4.42 PROForms fiberglass structural shapes and PROGrid fiberglass molded grating panels
- Figure 4.43 Bellagio Hotel and Casino fountain
- Figure 4.44: USCG Aids to Navigation (ATON) built using FRP piles. (USCG) (LT Jon Benvenuto, P.E. and Dan O'Connor, P.E. Composite Material in U.S Coast Guard Aids to Navigation)
- Figure 4.45 Subsea Cocoons
- Figure 5.1 FRP hexagonal super-deck
- Figure 5.2 FRP super-deck under 3-point loading
- Figure 5.3 Horse-type wicket gate configuration (left), timber wicket gate (right)
- Figure 5.4 Wicket gate in operating position
- Figure 5.5 Top bail (left) and bottom bail (right)
- Figure 5.6 Cross section of the FRP wicket gate (dimensions are in inches, 1 inch = 25.4 mm)
- Figure 5.7 Four-point bending test of FRP wicket gate
- Figure 5.8 Operating position of the gate
- Figure 5.9 Mitre gate
- Figure 5.10 Mitre block space
- Figure 5.11 East Lynn Lake Bridge: corroded steel piles, Cove Creek, WV, USA
- Figure 5.12 Close-up of corroded steel pile
- Figure 5.13 Close-up of shell placed around corroded steel pile
- Figure 5.14 Diagram of the repairs that will encapsulate and protect the piles from future corrosion
- Figure 5.15 Columns with shells in place and wrapped with GFRP wrap
- Figure 5.16 View of the bridge after rehabilitation (Photo by Dale Smith)
- Figure 5.17 Overview of the storm surge barrier with gates
- Figure 6.1 Infrared testing equipment – (a) low cost infrared camera (b) advanced infrared camera and (c) shop heater
- Figure 6.2 Advanced infrared testing equipment including pulsed and flashed heating and data processing computer
- Figure 6.3 Digital tap hammer
- Figure 6.4 Digital picture and (b) infrared image of the inner side of outer west beam in Muddy Creek Bridge
- Figure 6.5 Digital picture and corresponding infrared images of various debonded areas in the La Chein GFRP bridge deck

LIST OF TABLES

- Table 1.1 Related PIANC reports
- Table 2.1 Comparison in properties between FRP composites and other materials
- Table 5.1 Adjustment factors for end-use conditions (extract from Draft LRFD code)
- Table 5.2 Mechanical properties of FRP hexagonal super-deck
- Table 5.3 Four-point bending test results of FRP wicket gate