

INTERNATIONAL NAVIGATION  
ASSOCIATION



ASSOCIATION INTERNATIONALE  
DE NAVIGATION

## Inspection, Maintenance and Repair of Maritime Structures Exposed to Damage and Material Degradation caused by a Salt Water Environment

Revision of PIANC Report by PTC-II (MarCom) WG 17, 1990



MarCom  
Report of WG 17 - 2004

INTERNATIONAL NAVIGATION ASSOCIATION

### ACKNOWLEDGMENTS

#### 1. INTRODUCTION

- 1.1 Background
- 1.2 Related action
- 1.3 Abbreviations
- 1.4 Glossary

#### 2. SCOPE AND RECOMMENDATIONS

- 2.1 Port structures
- 2.2 Scope of the report
- 2.3 Guidance and recommendations

#### 3. PRINCIPLES AND CAUSES OF MATERIAL DEGRADATION AND DAMAGE

- 3.0 General
- 3.1 Timber
- 3.2 Stone and masonry

3.3	Concrete (unreinforced, reinforced and pre-stressed)
3.4	Steel
<b>4.</b>	<b>INSPECTION METHODS</b>
4.0	General
4.1	Timber
4.2	Stone, masonry and unreinforced concrete - general inspections
4.3	Reinforced and pre-stressed concrete - particular tests and analyses
4.4	Steel
<b>5.</b>	<b>MAINTENANCE AND PROTECTION PROCEDURES</b>
5.0	General
5.1	Timber
5.2	Stone and masonry
5.3	Concrete
5.4	Steel
<b>6.</b>	<b>REPAIR METHODS</b>
6.0	General
6.1	Timber
6.2	Stone and masonry
6.3	Concrete (unreinforced, reinforced and prestressed)
6.4	Steel
<b>7.</b>	<b>BIBLIOGRAPHY</b>
7.0	General
7.1	Timber
7.2	Stone, masonry and concrete (unreinforced)
7.3	Concrete (reinforced and prestressed)
7.4	Steel
<b>APPENDICES</b>	
A.	Deterioration of timber in port structures
B.	Cross-section illustrating deterioration of concrete structures in sea water
C.	Typical quay section for steel sheet (or tubular) pile walls